	Approved For Release 200	0/05/18	CONFIDENTIAL CIA-RDP82-00457R006000210010-5	
	CLASSIFICATION_	Spinister Street,	C-C1.72.01/00 0.7301/17 0.1	
COUNTR	Y Soviet Mone of Germany		REPORT NO.	14/201
TOPIC	Finsterwalde sirfield	WINDLE WARRANGER		
X1X	and the control of th	The second second	rango wego, rangokulu da jaya (174-144-144), wa nagoni wango nango nagoni wango pago kango kango kango kango k	
EVALUATI	ION	PLACE (OBTAINED25	X1A
	CONTENT	ulradors - Oplaniana o Spania	iski kanga an ayang kanga kanga kanga kanga an	
25X1A Date ob	TAINE	entrant . Here des apropries progra	_DATE_PREPARED 21 Sentember 3	350
REFEREN	ICES_	Melaliksi sepera Paks, mengan	TA ALL	
PAGES_	1 ENCLOSURES (NO. 8	: TYPE)	RETURN TO GIA	
REMARKS			LIBRARY	
			a that the part of the time of the secretary and secretary of the secretar	
		Apple and the second	alle and the second section which is a second to the second section and the second second second second second 	N (M. S.
	The second secon		MP half (das half an east-ghalfage, a that agus guarant go an halfage s na mail agus na ghalfa (das s s na an agus na an tha an ann agus agus tha an an agus na an tha an an agus agus agus agus agus agus agus agus	 We will restlict the Tell Matter that the Section of the International American specific problems.
25X1X	think place the security for the security in the process of the community of the community of the company of th	Wife - Western Maries	aller die der en einstelle einer werd der einstelle der der der der der der der der en en einstelle einstelle de delphase der einer der eine der der der der der der der der der de	
SOURCE				
1.	lio aircraft were statio ed	n Fin	stown older as whan's	
	been removed. An embandmen runway lighting or drainage of the field. Construction of the field. Sand and cru cement mixing machines and work was noticed at some hading in front of the hangers. The number of workers seemed	t. about acil: work; sled si construction ngars. presi	part of the field seemed to have grass cover and the construction hat ly meters high, which is indications, parallels the runway in this appeared to be contracted in the eastones are piled there and narrow-paction huts were also seen. Completabor details of six to eight meanably reconditioning the concrete we decreased. An of the serviceable before mid-October	uts had tive of section tern half tuge rails, eted repair n were work- aprons. 25X1X
25X1C				
		No Cla	Declassified ss. Changed To: TS S C ha: 188 a 70-2 a: 1978 By: 2-7	

CLASSIFICATION TO THE SECOND CONTROL OF THE